

Oil Field Environmental Incident Summary

Incident: 20151211154904 **Date/Time of Notice:** 12/11/2015 15:49

Responsible Party: SM ENERGY COMPANY

Well Operator: ST MARY LAND & EXPLORATION COMPANY

Well Name: OWL 1-28HS

Field Name: AMBROSE

Well File #: 31367

Date Incident: 12/10/2015 **Time Incident:** 08:00

Facility ID Number:

County: DIVIDE

Twp: 163

Rng: 99

Sec: 28

Qtr:

Location Description:

Submitted By: Jeniffer Sutherland

Received By:

Contact Person: Randy Carlson
PO BOX 7168
BILLINGS, MT 59103-7168

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	1	Barrels			1	barrels

Description of Other Released Contaminant:

Oil based mud

Inspected: **Written Report Received:** 12/24/2015 **Clean Up Concluded:** 12/6/2015

Risk Evaluation:

No immediate health risk as spill was contained and cleaned up immediately.

Areal Extent:

Potential Environmental Impacts:

No environmental impacts as spill was contained and cleaned up immediately.

Action Taken or Planned:

Initial fix is to add a secondary method to pull from the scalpin tank to manually remove fluid should it become necessary. They are currently planning this fix to be put in place during the rig move.

Wastes Disposal Location:

Agencies Involved: No additional agencies needed.

Updates

Date: 12/11/2015 **Status:** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a valve/piping connection leak, remained within diking according to the report. NDIC retains oversight.